




**SIERRA
ENERGY
PROFESSIONALS**



Building Envelope Test – Straw Bale Construction, Nevada City CA

Presented By:
Sierra Energy Professionals
P.O. Box 4112
Truckee, CA 96160

Millette Residence



**19480 Chalk Bluff Rd.
Nevada City, CA 95959**

Introduction:

Sierra Energy Professionals, David Arkin, Jim Seely and Eric Millette collaborated to conduct a test on the tightness of the building envelope of this residence. The system was analyzed by using a testing method known as a Blower Door. The house was shut off to the exterior and pressurized, which allowed for inefficiencies to be identified with a pressure meter, infrared camera, and a fog machine.

History:

The residence is located at 19480 Chalk Bluff Rd. Nevada City, CA and was completed about a year ago. It is a hybrid construction with wood framing used for the bathroom and straw bales for the rest of construction. The roof was constructed using Structurally Insulated Panels (SIP's). The house has aluminum framed windows, all double paned. No areas of discomfort are reported and all systems function well.

Building Envelope Testing:



Figure 1: Blower Door setup.

Depressurization: A Blower Door test (**Figure 1**) was set up on the front door, with the fan set to depressurize the interior of the house to negative 50 Pascals(Pa) relative to the exterior. This approximates a 20 mph wind hitting the house on all sides and causes air to infiltrate from the exterior to the interior living space.

When the house pressure was at a 50 Pa difference relative to the exterior, the flow of air infiltrating from outside into the building envelope was measured to be **617 cubic feet per minute (CFM)**. This is the **equivalent of an 81 square inch (less than 1 square foot)** window being open on a flat wall all the time. This is a very low number and no improvements are seen as necessary in this area. The American Society of Heating, Refrigeration, and Air Conditioning Engineers (ASHRAE) suggest a minimum natural ventilation of 950 – 1,200 CFM for a house of this size. This house is tighter than ASHRAE suggests without mechanical ventilation but occupant knowledge and behavior surpasses any need for that.

Building Envelope Infrared Inspection

Figures 2 – 28 show air and thermal infiltration. Infrared images will be on the left and visual images on the right. Green and blue represent cooler temperatures while orange/red/yellow/white represent the temperature getting hotter. From the exterior the lighter colors represent heated air from the interior escaping. From the interior darker/bluer colors represent cold air infiltrating from the exterior.




Figure 2a:
Infrared Image
Windows on south side of house above sliding glass door from exterior. Only thermal movement is from bridging across frame. Very well sealed window.



Figure 2b: Visual Image




Figure 3a:
Infrared Image
windows to right of sliding glass door. No air leakage.



Figure 3b: Visual Image




Figure 4a:
Infrared Image
sliding glass door.
Minor air
movement around
edges especially
left side. Other
thermal
movement due to
radiant heat.



Figure 4b: Visual
Image




Figure 5a:
Infrared Image
exterior corner of
"bed nook".
Looks very good
basically no
leakage



Figure 5b: Visual
Image




Figure 6a:
Infrared Image exterior of house looks very good. Possible leakage or bridging in bottom right from foundation connection of bathroom.




Figure 6b: Visual Image



Figure 7a:
Infrared Image bathroom no air leakage just bridging from foundation.



Figure 7b: Visual Image




Figure 8a: Infrared Image front door. Possibly some leakage from penetration to upper left of door. Everything else good.



Figure 8b: Visual Image




Figure 9a: Infrared Image pipe penetration above front door. Probably residual heat from venting, could be minor infiltration issue.



Figure 9b: Visual Image




Figure 10a:
Infrared Image
north wall looks
good. Note lack
of bridging at
foundation.



Figure 10b:
Visual Image




Figure 11a:
Infrared Image
west side of
house. Red up
higher is heat gain
from the sun.



Figure 11b:
Visual Image




Figure 12a: Hot water distribution visible in wall behind hot water solar panels. Mechanical room on other side pumps hot water down that corner.



Figure 12b: Visual Image




Figure 13a: Infrared Image heat escaping through the foundation slab. Even though it is insulated from the hydronic section it still provides a thermal bridge to the exterior.



Figure 13b: Visual Image




Figure 14a:
Infrared Image of corner by "bed nook". Note foundation bridging.



Figure 14b:
Visual Image




Figure 15a:
Interior floor edge by refrigerator. No bridging from floor to exterior foundation visible, but not exposed on exterior like other areas.



Figure 15b:
Visual Image




Figure 16a:
Infrared Image
door from
bathroom to
exterior before
Blower Door test.



Figure 16b:
Visual Image




Figure 17a:
Infrared Image
bathroom door at
very start of
Blower Door test.



Figure 17b:
Visual Image




Figure 18a:
Infrared Image
bathroom door
after 5 minutes of
Blower Door
testing. Note very
slight growth of
blue line on left
side of door, this
is a well sealed
door.




Figure 18b:
Visual Image




Figure 19a:
Infrared Image
entryway
windows no
apparent leakage
just thermal
bridging.




Figure 19b:
Visual Image




Figure 20a:
Infrared Image
bathroom
windows. Look
good no
infiltration.




Figure 20b:
Visual Image




Figure 21a:
Infrared Image
loft windows.
Note area of
infiltration in top
left corner. A gap
was seen on close
visual inspection.




Figure 21b:
Visual Image




Figure 22a:
Infrared Image
living room
window. All
thermal bridging
transfer.




Figure 22b:
Visual Image




Figure 23a:
Infrared Image
upper corner
living room
windows. Heat is
due to sun
warming. Note a
bit of infiltration
in upper corner at
wall/ceiling
interface.



Figure 23b:
Visual Image




Figure 24a:
Infrared Image
upper corner
kitchen windows.
Possibly some
leakage along
joints and up into
corner.



Figure 24b:
Visual Image




Figure 25a:
Infrared Image
"bed nook"
windows. Look
good.



Figure 25b:
Visual Image




Figure 26a:
Infrared Image
"bed nook
windows".
Corner might
show some
infiltration.




Figure 26b:
Visual Image




Figure 27a:
Infrared Image
well sealed
chimney flashing
some radiative
transfer.



Figure 27b:
Visual Image




Figure 28a:
Wood burning stove. Leakage from flue is basically unavoidable, good shielding at chimney helps.



Figure 28b:
Visual Image



Figure 29: Very minor infiltration of fog in bottom right corner of right window during house depressurization.

Figure 30: Visual illustration of fog entering through small leakage area of sliding glass door during house depressurization.

